

Advanced Materials**Araldite® XU 3508* / Aradur® 917* / Accelerator DY 070*****TOUGHENED HOT CURING EPOXY SYSTEM**

Resin XU 3508 (toughened epoxy resin)
 Aradur® 917 (anhydride hardener)
 Accelerator DY 070 (imidazole accelerator)

APPLICATIONS	High performance composites.		
PROPERTIES	Anhydride-cured matrix system with extremely long pot life. The reactivity of the system is adjustable by variation of the accelerator content. The system is easy to process and exhibits excellent mechanical, dynamic and thermal properties.		
PROCESSING	<ul style="list-style-type: none"> Filament Winding Pultrusion Pressure Moulding 		
KEY DATA	Araldite® XU 3508		
	Aspect (visual)	white liquid	
	Epoxy content (ISO 3000)	4.80 - 5.20	[eq/kg]
	Viscosity at 25 °C (ISO 2555)	11000 - 20000	[mPa s]
	Density at 25 °C (ISO 1675)	1.15 - 1.20	[g/cm ³]
	Flash point (ISO 2719)	200	[°C]
	Storage temperature (see expiry date on original container)	2 - 40 °C	[°C]
	Aradur® 917		
	Aspect (visual)	clear liquid	
	Colour (Gardner, ISO 4630)	≤ 2	
	Viscosity at 25 °C (ISO 12058-1)	50 - 100	[mPa s]
	Density at 25 °C (ISO 1675)	1.20 - 1.25	[g/cm ³]
	Flash point (ISO 2719)	195	[°C]
	Storage temperature (see expiry date on original container)	2 - 40 °C	[°C]
	Accelerator DY 070		
	Aspect (visual)	clear liquid	
	Colour (Gardner, ISO 4630)	≤ 9	
	Viscosity at 25 °C (ISO 12058-1)	≤ 50	[mPa s]
	Density at 25 °C (ISO 1675)	0.95 - 1.05	[g/cm ³]
	Flash point (ISO 2719)	92	[°C]
	Storage temperature (see expiry date on original container)	2 - 40 °C	[°C]

* In addition to the brand name product denomination may show different appendices, which allows us to differentiate between our production sites: e.g., BD = Germany, US = United States, IN = India, CI = China, etc.. These appendices are in use on packaging, transport and invoicing documents. Generally the same specifications apply for all versions. Please address any additional need for clarification to the appropriate Huntsman contact.

STORAGE	<p>Provided that Araldite® XU 3508, Aradur® 917 and Accelerator DY 070 are stored in a dry place in their original, properly closed containers at the above mentioned storage temperatures they will have the shelf lives indicated on the labels. Partly emptied containers should be closed immediately after use. Because Aradur® 917 is sensitive to moisture, storage containers should be ventilated with dry air only.</p>
----------------	---

PROCESSING DATA

MIX RATIO	<i>Components</i>	<i>Parts by weight</i>	<i>Parts by volume</i>
	Araldite® XU 3508	100	100
	Aradur® 917	90	86
	Accelerator DY 070	0.5 - 2	0.6 - 2.4

We recommend that the components are weighed with an accurate balance to prevent mixing inaccuracies which can affect the properties of the matrix system. The components should be mixed thoroughly to ensure homogeneity. It is important that the side and the bottom of the vessel are incorporated into the mixing process. When processing large quantities of mixture the pot life will decrease due to exothermic reaction. It is advisable to divide large mixes into several smaller containers.

PROCESSING RECOMMENDATIONS

To simplify the mixing process the resin can be preheated to about 30 °C to 50 °C before adding the cold hardener. Hardener and accelerator can be premixed, thus allowing the use of two component mixing/metering equipment. The mix of hardener and accelerator has a shelf life of several days. The processing of the system at elevated temperatures of 30 °C to 40 °C shows the best results. The gelation temperature should not be higher than absolutely necessary. A high gelation temperature induces high shrinkage and generates internal stresses.

ALL THE MENTIONED VALUES ARE DETERMINED BY 1 PBW. OF ACCELERATOR DY 070**INITIAL MIX VISCOSITY**

(CONE PLATE VISCOSIMETER)	at 25°C	<i>[mPas]</i>	580 - 680
---------------------------	---------	---------------	-----------

POT LIFE

(TECAM, 65 % RH, 100 G)	at 23°C	<i>[h]</i>	100 - 110
-------------------------	---------	------------	-----------

GEL TIME

(HOT PLATE)	at 120°C	<i>[min]</i>	8 - 11
	at 140°C	<i>[min]</i>	2 - 4

The values shown are for small amounts of pure resin/hardener mix. In composite structures the gel time can differ significantly from the given values depending on the fibre content and the laminate thickness.

TYPICAL CURE CYCLES

Gelation either	2 - 4 h at 80 °C
or	1 - 3 h at 90 °C
Post-cure either	4 - 8 h at 120 °C
or	2 - 8 h at 140 °C

PROPERTIES OF THE CURED, NEAT FORMULATION

GLASS TRANSITION TEMPERATURE (TG) (IEC 1006, 10 K/MIN)	<i>Cure:</i>		<i>T_G DSC [°C]</i>
	4 h 80 °C + 4 h 120 °C		130 - 140
	4 h 80 °C + 8 h 140 °C		135 - 145
FLEXURAL TEST (ISO 178)	<i>Cure: 4h 80°C + 8h 140°C</i>		
	Flexural strength	[MPa]	140 - 150
	Elongation at flexural strength	[%]	5.5 - 6.5
	Ultimate strength	[MPa]	138 - 148
	Ultimate elongation	[%]	5.7 - 6.7
	Flexural modulus	[MPa]	2900 - 3200
FRACTURE PROPERTIES BEND NOTCH TEST (PM 258-0/90)	<i>Cure: 4h 80°C + 8h 140°C</i>		
	Fracture toughness K _{1C}	[MPa√m]	0.85 - 0.95
	Fracture energy G _{1C}	[J/m ²]	210 - 240
WATER ABSORPTION (ISO 62)	<i>Cure: 4h 80°C + 8h 140°C</i>		
	<i>Immersion:</i> 10 days H ₂ O 23 °C	[%]	0.40 - 0.46

HANDLING PRECAUTIONS**Personal hygiene***Safety precautions at workplace*

protective clothing	yes
gloves	essential
arm protectors	recommended when skin contact likely
goggles/safety glasses	yes

Skin protection

before starting work	Apply barrier cream to exposed skin
after washing	Apply barrier or nourishing cream

Cleansing of contaminated skin

Dab off with absorbent paper, wash with warm water and alkali-free soap, then dry with disposable towels. Do not use solvents

Disposal of spillage

Soak up with sawdust or cotton waste and deposit in plastic-lined bin

Ventilation

of workshop	Renew air 3 to 5 times an hour
of workplaces	Exhaust fans. Operatives should avoid inhaling vapours

FIRST AID

Contamination of the eyes by resin, hardener or mix should be treated immediately by flushing with clean, running water for 10 to 15 minutes. A doctor should then be consulted.

Material smeared or splashed on the *skin* should be dabbed off, and the contaminated area then washed and treated with a cleansing cream (see above). A doctor should be consulted in the event of severe irritation or burns. Contaminated clothing should be changed immediately.

Anyone taken ill after *inhaling* vapours should be moved out of doors immediately.

In all cases of doubt call for medical assistance.

IMPORTANT LEGAL NOTICE

Huntsman Advanced Materials warrants only that its products meet the specifications agreed with the user. Typical properties, where stated, are to be considered as representative of current production and should not be treated as specifications.

The manufacture of materials is the subject of granted patents and patent applications; freedom to operate patented processes is not implied by this publication.

While all the information and recommendations in this publication are, to the best of Huntsman Advanced Material's knowledge, information and belief, accurate at the date of publication, NOTHING HEREIN IS TO BE CONSTRUED AS A WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING BUT WITHOUT LIMITATION, AS TO MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. IN ALL CASES, IT IS THE RESPONSIBILITY OF THE USER TO DETERMINE THE APPLICABILITY OF SUCH INFORMATION AND RECOMMENDATIONS AND THE SUITABILITY OF ANY PRODUCT FOR ITS OWN PARTICULAR PURPOSE.

The behaviour of the products referred to in this publication in manufacturing processes and their suitability in any given end-use environment are dependent upon various conditions such as chemical compatibility, temperature, and other variables, which are not known to Huntsman Advanced Materials. It is the responsibility of the user to evaluate the manufacturing circumstances and the final product under actual end-use requirements and to adequately advise and warn purchasers and users thereof.

Products may be toxic and require special precautions in handling. The user should obtain Safety Data Sheets from Huntsman Advanced Materials containing detailed information on toxicity, together with proper shipping, handling and storage procedures, and should comply with all applicable safety and environmental standards.

Hazards, toxicity and behaviour of the products may differ when used with other materials and are dependent on manufacturing circumstances or other processes. Such hazards, toxicity and behaviour should be determined by the user and made known to handlers, processors and end users.

Except where explicitly agreed otherwise, the sale of products referred to in this publication is subject to the general terms and conditions of sale of Huntsman Advanced Materials LLC or of its affiliated companies including without limitation, Huntsman Advanced Materials (Europe) BVBA, Huntsman Advanced Materials Americas Inc., and Huntsman Advanced Materials (Hong Kong) Ltd.

Huntsman Advanced Materials is an international business unit of Huntsman Corporation. Huntsman Advanced Materials trades through Huntsman affiliated companies in different countries including but not limited to Huntsman Advanced Materials LLC in the USA and Huntsman Advanced Materials (Europe) BVBA in Europe.

Aradur and Araldite are registered trademarks of Huntsman Corporation or an affiliate thereof.

Copyright © 2007 Huntsman Corporation or an affiliate thereof. All rights reserved.

Main Office :
Huntsman Advanced Materials (Switzerland) GmbH
Klybeckstrasse 200
CH-4057 BASEL
Switzerland
+41 61 966 3333